

## EAST Search History

| Ref # | Hits | Search Query  | DBs                          | Default Operator | Plurals | Time Stamp          |
|-------|------|---|------------------------------|------------------|---------|---------------------|
| S2    | 5168 | "suspended ceiling"   | US-PGPUB;<br>USPAT           | AND              | ON      | 2007/09/18<br>11:55 |
| S3    | 1105 | S1 S2   | US-PGPUB;<br>USPAT           | AND              | ON      | 2007/09/18<br>11:55 |
| S4    | 107  | S1 S2 replace   | US-PGPUB;<br>USPAT           | AND              | ON      | 2007/09/18<br>11:56 |
| S5    | 0    | ("modularbuilding").PN.   | US-PGPUB;<br>USPAT           | OR               | OFF     | 2007/11/08<br>10:09 |
| S6    | 0    | ("modularbuilding").PN.   | US-PGPUB;<br>USPAT           | OR               | OFF     | 2007/11/08<br>10:09 |
| S7    | 0    | S6  | US-PGPUB;<br>USPAT           | AND              | ON      | 2007/11/08<br>10:10 |
| S8    | 1613 | "modular building"  | US-PGPUB;<br>USPAT           | AND              | ON      | 2007/11/08<br>10:10 |
| S9    | 0    | "modular building""0"   | US-PGPUB;<br>USPAT           | AND              | ON      | 2007/11/08<br>10:59 |
| S10   | 19   | "6250022"   | US-PGPUB;<br>USPAT           | AND              | ON      | 2007/11/08<br>11:03 |
| S11   | 27   | ("1229477"   "2078011"  <br>"2336435"   "3500596"  <br>"3566554"   "4633626"  <br>"5331778"   "5724774"  <br>"5890338"   "5975660").PN. OR<br>("6250022").URPN. | US-PGPUB;<br>USPAT;<br>USOCR | AND              | ON      | 2007/11/08<br>11:13 |
| S12   | 396  | 52/79.9   | US-PGPUB;<br>USPAT;<br>USOCR | AND              | ON      | 2007/11/08<br>13:24 |
| S13   | 101  | 52/79.3   | US-PGPUB;<br>USPAT;<br>USOCR | AND              | ON      | 2007/11/08<br>13:46 |
| S14   | 161  | 52/92.1   | US-PGPUB;<br>USPAT;<br>USOCR | AND              | ON      | 2007/11/08<br>13:52 |
| S15   | 223  | 52/92.2   | US-PGPUB;<br>USPAT;<br>USOCR | AND              | ON      | 2007/11/08<br>13:56 |
| S16   | 52   | 52/745.11   | US-PGPUB;<br>USPAT;<br>USOCR | AND              | ON      | 2007/11/08<br>14:03 |
| S17   | 169  | 52/745.06   | US-PGPUB;<br>USPAT;<br>USOCR | AND              | ON      | 2007/11/08<br>14:07 |
| S18   | 904  | 52/27   | US-PGPUB;<br>USPAT;<br>USOCR | AND              | ON      | 2007/11/08<br>14:11 |

|     |      |   |                              |     |    |                     |
|-----|------|---|------------------------------|-----|----|---------------------|
| S19 | 561  | 52/79.5   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>14:23 |
| S20 | 399  | 52/36.4   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>14:31 |
| S21 | 203  | 52/36.6   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>14:33 |
| S22 | 63   | 52/81.5   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>14:35 |
| S23 | 1372 | 52/79.1   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>14:35 |
| S24 | 356  | 52/90.1   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>14:36 |
| S25 | 208  | 52/126.3  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>14:37 |
| S26 | 504  | 52/262  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>14:40 |
| S27 | 27   | ("1229477"   "2078011"  <br>"2336435"   "3500596"  <br>"3566554"   "4633626"  <br>"5331778"   "5724774"  <br>"5890338"   "5975660").PN. OR<br>("6250022").URPN. | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>14:42 |
| S28 | 452  | 312/100   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>14:46 |
| S29 | 1042 | 312/108   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>14:47 |
| S30 | 3038 | "tilt up"   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>14:47 |
| S31 | 21   | S30 interengaging   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>14:48 |
| S32 | 594  | S30 building  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>14:49 |
| S33 | 257  | 52/289  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>15:09 |
| S34 | 693  | "composite building"  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>15:17 |

|     |       |  |                              |     |    |                     |
|-----|-------|--|------------------------------|-----|----|---------------------|
| S35 | 83    | "composite building"<br>interconnecting              | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>15:17 |
| S36 | 42    | "composite building"<br>interconnecting roof         | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>15:17 |
| S37 | 38203 | prefab\$   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>15:24 |
| S38 | 7727  | prefab\$ (building system)                           | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>15:24 |
| S39 | 64    | prefab\$ (building system)"tilt-up"                  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>15:24 |
| S40 | 2797  | prefab\$ (building system)roof                       | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>15:27 |
| S41 | 48    | prefab\$ (building system) (roof<br>near connecting) | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>15:28 |
| S42 | 4     | flat near roof "steel girders"                       | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>15:36 |
| S43 | 3183  | flat adj roof  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>15:37 |
| S44 | 1178  | S43 connecting                                       | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>15:38 |
| S45 | 736   | S44 "building"                                       | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>15:38 |
| S46 | 3     | S43 near steel                                       | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>15:41 |
| S47 | 116   | S43 girders  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/08<br>15:42 |
| S48 | 8233  | "roof structure"                                     | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/09<br>08:36 |
| S49 | 283   | "roof structure" girders                             | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/09<br>08:37 |
| S50 | 0     | ("2003/0172516").URPN.                               | USPAT                        | AND | ON | 2007/11/09<br>08:44 |

|     |        |  |                              |     |    |                     |
|-----|--------|--|------------------------------|-----|----|---------------------|
| S51 | 30     | ("3170269"   "3350828"  <br>"3482367"   "3591993"  <br>"4037377"   "4125984"  <br>"4443988"   "4837999"  <br>"4989386"   "5021108"  <br>"5121583"   "5152114"  <br>"5497589"   "5638651"  <br>"5842315"   "6085485").PN. OR<br>("6256960").URPN. | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>08:52 |
| S52 | 0      | sna adj in near roof   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:13 |
| S53 | 0      | snap adj in near roof  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:13 |
| S54 | 0      | "snap in" near roof  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:13 |
| S55 | 0      | "lock in" near roof  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:13 |
| S56 | 60     | "interlock" near roof  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:14 |
| S57 | 32     | "modular roof panels"  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:19 |
| S58 | 11     | "snap in" roof   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:26 |
| S59 | 4      | "lock in" roof   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:26 |
| S60 | 242786 | boss   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:27 |
| S61 | 8088   | boss roof  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:27 |
| S62 | 90     | boss roof girders  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:27 |
| S63 | 0      | boss roof (prefab4)  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:29 |
| S64 | 154    | boss roof (prefab\$)   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:29 |
| S65 | 108    | "tilt-up construction"   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:39 |

|     |        |  |                              |     |    |                     |
|-----|--------|--|------------------------------|-----|----|---------------------|
| S66 | 36     | waall  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:47 |
| S67 | 109555 | wall roof  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:47 |
| S68 | 52226  | S67 system   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:47 |
| S69 | 20441  | S67 system (interconnect or engaged or lock)                 | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:48 |
| S70 | 4725   | S67 system (interconnect)                                    | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:49 |
| S71 | 1780   | S67 system (interconnect)building                            | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>09:50 |
| S72 | 551    | S67 system (interconnect)building modular                    | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>10:02 |
| S73 | 0      | ("2007/0193186").URPN.                                       | USPAT                        | AND | ON | 2007/11/09<br>10:02 |
| S74 | 6938   | roof near wall   | USPAT                        | AND | ON | 2007/11/09<br>10:09 |
| S75 | 22     | S74 near (engaging or lock\$ or snap or connect)             | USPAT                        | AND | ON | 2007/11/09<br>10:10 |
| S76 | 123    | 52/763   | USPAT                        | AND | ON | 2007/11/09<br>10:12 |
| S77 | 4      | ("3182769"   "3886705"   "4201024").PN. OR ("5896717").URPN. | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>10:25 |
| S78 | 100    | 52/774   | USPAT                        | AND | ON | 2007/11/09<br>10:31 |
| S79 | 92     | 52/571   | USPAT                        | AND | ON | 2007/11/09<br>10:35 |
| S80 | 928    | 52/698   | USPAT                        | AND | ON | 2007/11/09<br>10:36 |
| S81 | 297    | 52/272   | USPAT                        | AND | ON | 2007/11/09<br>10:37 |
| S82 | 51     | 52/448   | USPAT                        | AND | ON | 2007/11/09<br>10:49 |
| S83 | 0      | "snap in" near roof  | EPO; JPO                     | AND | ON | 2007/11/09<br>10:50 |
| S84 | 3      | "interlock" near roof  | EPO; JPO                     | AND | ON | 2007/11/09<br>10:54 |
| S85 | 91     | boss roof  | EPO; JPO                     | AND | ON | 2007/11/09<br>10:55 |
| S86 | 216    | walls roof (interlock or \$engageor engage\$ or connect)     | EPO; JPO                     | AND | ON | 2007/11/09<br>10:56 |

|      |       |  |                        |     |    |                  |
|------|-------|--|------------------------|-----|----|------------------|
| S87  | 745   | walls roof (interlock or \$engage or engage\$ or connect)  | EPO; JPO               | AND | ON | 2007/11/09 11:03 |
| S88  | 8     | walls roof (interlock or \$engage or engage\$ or connect) modular  | EPO; JPO               | AND | ON | 2007/11/09 11:03 |
| S89  | 8     | walls roof (interlock or \$engage or engage\$ or connect) tilt   | EPO; JPO               | AND | ON | 2007/11/09 11:04 |
| S90  | 2423  | "roof Structure"   | EPO; JPO               | AND | ON | 2007/11/09 11:04 |
| S91  | 34    | "roof Structure" (interconnect or \$engage)  | EPO; JPO               | AND | ON | 2007/11/09 11:05 |
| S92  | 1840  | "building construction"  | EPO; JPO               | AND | ON | 2007/11/09 11:06 |
| S93  | 176   | "building construction" roof   | EPO; JPO               | AND | ON | 2007/11/09 11:06 |
| S94  | 1     | "building construction" roof lock  | EPO; JPO               | AND | ON | 2007/11/09 11:07 |
| S95  | 34    | "modular building system"  | EPO; JPO               | AND | ON | 2007/11/09 11:50 |
| S96  | 15    | "engage" roof and wall and projections   | EPO; JPO               | AND | ON | 2007/11/09 11:53 |
| S97  | 10480 | "engage" roof and wall and projections   | US-PGPUB; USPAT; USOCR | AND | ON | 2007/11/09 11:54 |
| S98  | 1202  | "engage" roof and wall and projections enclosure   | US-PGPUB; USPAT; USOCR | AND | ON | 2007/11/09 11:55 |
| S99  | 1634  | roof near (connect or engage)  | US-PGPUB; USPAT; USOCR | AND | ON | 2007/11/09 12:02 |
| S100 | 0     | S99 near "building construction"   | US-PGPUB; USPAT; USOCR | AND | ON | 2007/11/09 12:02 |
| S101 | 8     | S99 near "building"  | US-PGPUB; USPAT; USOCR | AND | ON | 2007/11/09 12:03 |
| S102 | 251   | S99 near30 wall  | US-PGPUB; USPAT; USOCR | AND | ON | 2007/11/09 12:04 |
| S103 | 77    | ("0603147"   "2079635"   "2270161"   "2981383"   "3070646"   "3381430"   "3436881"   "3452501"   "3513608"   "3516216"   "3543456"   "3638385"   "3640039"   "3675380"   "3820299"   "3854269"   "3866381"   "3992839"   "4258519"   "4294051"   "4447099"   "4557091"   "4652170"   "4805365"   "5036634"   "5155961"   "5184436"   "5221131" | US-PGPUB; USPAT; USOCR | AND | ON | 2007/11/09 12:12 |

|      |    |   |                              |     |    |                     |
|------|----|---|------------------------------|-----|----|---------------------|
|      |    | "5331778"   "5372415"  <br>"5386788"   "5398909"  <br>"5413236"   "5466058"  <br>"5529423"   "5575119"  <br>"5592794"   "5605344"  <br>"5622010"   "5647181"  <br>"5664380"   "5673531"  <br>"5724774"   "5775046"  <br>"5813738"   "5864997"  <br>"5975660"   "6047663"  <br>"6053591"   "6099092"  <br>"6105794"   "6113203"  <br>"6185878"   "6202867"  <br>"6250022"   "6357194"  <br>"D420838").PN. OR ("6701678").<br>URPN. |                              |     |    |                     |
| S104 | 52 | ("0975692"   "1924414"  <br>"2751635"   "3039569"  <br>"3256860"   "3299594"  <br>"3484999"   "3501875"  <br>"3512316"   "3566554"  <br>"3593471"   "3643689"  <br>"3690077"   "3707811"  <br>"3838545"   "3899043"  <br>"3992829"   "4102091"  <br>"4505078"   "4592175"  <br>"4637179"   "4644708"  <br>"4726155"   "4822197"  <br>"4854094"   "5285604").PN. OR<br>("5724774").URPN.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:18 |
| S105 | 17 | ("2057942"   "2691242"  <br>"3442311"   "3692201"  <br>"3844083"   "4035965"  <br>"4173287"   "4874341"  <br>"5118547"   "5357728"  <br>"5400178"   "5895045"  <br>"6488153"   "6665993").PN. OR<br>("7155865").URPN.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:22 |
| S106 | 23 | ("3564786"   "3710521"  <br>"3754364"   "3792558"  <br>"3822519"   "3824750"  <br>"3835601"   "3852924"  <br>"3881283"   "3900994"  <br>"3940890"   "3982732"  <br>"4098039"   "4221441"  <br>"4398378"   "4447996"  <br>"4545158"   "4807407"  <br>"5435476"   "5643488"  <br>"5782047"   "5867964").PN.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:23 |
| S107 | 18 | ("5293725").URPN.   | USPAT                        | AND | ON | 2007/11/09<br>12:25 |

|      |    |   |                              |     |    |                     |
|------|----|---|------------------------------|-----|----|---------------------|
| S108 | 32 | ("2618039"   "3215389"  <br>"3372519"   "3559944"  <br>"3600870"   "3706168"  <br>"3724143"   "3730475"  <br>"3750366"   "3772835"  <br>"3814374"   "3847521"  <br>"3898776"   "3990193"  <br>"4038798"   "4050213"  <br>"4068430"   "4127971"  <br>"4185423"   "4211043"  <br>"4240236"   "4244682"  <br>"4252292"   "4650150"  <br>"4886234"   "5524861"  <br>"5643488"   "5893241"  <br>"6058672").PN. | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:27 |
| S109 | 8  | ("3074080"   "3356183"  <br>"3822569"   "3990197"  <br>"5035077"   "5210985").PN.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:28 |
| S110 | 15 | ("1653126"   "3574981"  <br>"3675885"   "3700202"  <br>"3727885"   "3885361"  <br>"4068427"   "4083156"  <br>"4872634"   "5322404"  <br>"5634301"   "5938391"  <br>"5943830"   "6029407").PN.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:30 |
| S111 | 29 | ("2058386"   "2357819"  <br>"3033330"   "3078968"  <br>"3111202"   "3195191"  <br>"3292328"   "3494405"  <br>"3583466"   "3596701"  <br>"3823523"   "3897668"  <br>"3986312"   "4471548"  <br>"4516620"   "4546591"  <br>"4612848"   "4708189"  <br>"5471805"   "5487402"  <br>"5735100").PN. OR ("6050045").<br>URPN.  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:31 |
| S112 | 27 | ("4429850"   "4726554"  <br>"4805783"   "4809479"  <br>"5228579"   "5409120"  <br>"5622010"   "5655674"  <br>"5775521"   "5791093"  <br>"5857578"   "5890607"  <br>"5941026"   "5944203"  <br>"6098363"   "6349507"  <br>"6397534"   "6763957"  <br>"6945414"   "7093726"  <br>"7104023"   "D302086"  <br>"D393907"   "D404148"  <br>"D426089"   "D511581"  <br>"D533283").PN. OR ("D551470").<br>URPN.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:32 |



|      |     |   |                              |     |    |                     |
|------|-----|---|------------------------------|-----|----|---------------------|
| S113 | 27  | ("1229477"   "2078011"  <br>"2336435"   "3500596"  <br>"3566554"   "4633626"  <br>"5331778"   "5724774"  <br>"5890338"   "5975660").PN. OR<br>("6250022").URPN.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:33 |
| S114 | 9   | ("2010294"   "3529389"  <br>"4276730"   "4616459"  <br>"4896469"   "5411782"  <br>"6233891").PN.  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:34 |
| S115 | 17  | ("1321213"   "1843112"  <br>"2005958"   "2110110"  <br>"2154390"   "4023324"  <br>"4058948"   "4953332"  <br>"5146726"   "5373675"  <br>"5678378"   "5802792").PN.  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:36 |
| S116 | 21  | ("0152340"   "0770050"  <br>"0796433"   "1181934"  <br>"1729935"   "2793407"  <br>"3090086"   "3365222"  <br>"3601428"   "3683429"  <br>"3901611"   "3914914"  <br>"4005556").PN.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:41 |
| S117 | 0   | ("2005/0076605").URPN.  | USPAT                        | AND | ON | 2007/11/09<br>12:43 |
| S118 | 208 | ("0518292"   "1124404"  <br>"1129658"   "1131479"  <br>"1238858"   "1313630"  <br>"1363391"   "1421007"  <br>"1436033"   "1439281"  <br>"1499572"   "1537278"  <br>"1592070"   "1593424"  <br>"1657441"   "1725200"  <br>"1753451"   "1757763"  <br>"1773168"   "1778345"  <br>"1834892"   "1840304"  <br>"1854633"   "1893636"  <br>"1934760"   "1988124"  <br>"1988388"   "2006300"  <br>"2058285"   "2075262"  <br>"2111577"   "2184464"  <br>"2208589"   "2228363"  <br>"2262127"   "2266007"  <br>"2306548"   "2321813"  <br>"2451951"   "2467115"  <br>"2514805"   "2592634"  <br>"2630614"   "2723107"  <br>"2775019"   "2780936"  <br>"2823426"   "2823442"  <br>"2902745"   "2924962"  <br>"2993637"   "3146497"  <br>"3170269"   "3245185"  <br>"3246828"   "3295818"  <br>"3310917"   "3317178"  <br>"3330437"   "3341998"  <br>"3380703"   "3415023"  <br>"3434689"   "3435580" | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:44 |

|      |    |  |                              |     |    |                     |
|------|----|--|------------------------------|-----|----|---------------------|
|      |    | "3515779"   "3529389"  <br>"3534515"   "3553797"  <br>"3623288"   "3638902"  <br>"3707815"   "3818661"  <br>"3885008"   "3886699"  <br>"3892098"   "3906665"  <br>"3927498"   "3930633"  <br>"3971172"   "3979863"  <br>"4005559"   "4017051"  <br>"4033545"   "4090336"  <br>"4141532"   "4159100"  <br>"4163349"   "4176504"  <br>"4194333"   "4241555"  <br>"4291513"   "4365453"  <br>"4380887"   "4422997"  <br>"4426060"   "4432176"  <br>"4494353"   "4512126"  <br>"4532745"   "4542613"  <br>"4554124"   "4570398"  <br>"4605529"   "4619032"  <br>"4624089"   "4641468"  <br>"4726153"   "4726157"  <br>"4751803"   "4815243"  <br>"4841702"   "4862660"  <br>"4878323"   "4934121"  <br>"4947600"   "4974381"  <br>"5055252"   "5313753"  <br>"5335470"   "5357721"  <br>"5381635"   "5384993"  <br>"5398468"   "5442887"  <br>"5448871").PN. OR ("5560156"  <br>"5588272"   "5640822"  <br>"5697189"   "5699639"  <br>"5732524"   "5865001"  <br>"Re15979").PN. OR ("6151843").<br>URPN. |                              |     |    |                     |
| S119 | 20 | ("1696104"   "1820869"  <br>"1889138"   "2047062"  <br>"2467581"   "2575758"  <br>"2617160"   "3236014"  <br>"3747290"   "4114338"  <br>"4872297"   "5425207").PN.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:49 |
| S120 | 19 | ("3170269"   "3350828"  <br>"3482367"   "3591993"  <br>"4037377"   "4125984"  <br>"4443988"   "4837999"  <br>"4989386"   "5021108"  <br>"5121583"   "5152114"  <br>"5497589"   "5638651"  <br>"5842315"   "6085485").PN.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:52 |

|      |    |  |                              |     |    |                     |
|------|----|--|------------------------------|-----|----|---------------------|
| S121 | 69 | (<br>"2915150"   "2934180"  <br>"3253849"   "3662507"  <br>"3729889"   "3783563"  <br>"3791912"   "3921355"  <br>"4074489"   "4078348"  <br>"4263762"   "4282697"  <br>"4455793"   "4557091"  <br>"4615155"   "4621467"  <br>"4689926"   "4754587"  <br>"4777774"   "4802319"  <br>"4924641"   "4974383"  <br>"5007222"   "5285607"  <br>"5287675"   "5331782"  <br>"5353563"   "5412918"  <br>"5416139"   "5594202"  <br>"5676486"   "5685124"  <br>"5706620"   "5735090"  <br>"5792539"   "5890334"  <br>"6006480"   "6037033"  <br>"6044603"   "6092862"  <br>"6122877"   "6178709"  <br>"6250037"   "6256959"  <br>"6256960"   "6314704"  <br>"6378264"   "6412243"  <br>"6413610"   "6438923"  <br>"6455131"   "6481172"  <br>"6493995"   "6514368"  <br>"6564521"   "6568582"  <br>"6571523"   "6574938"  <br>"6584740"   "6584742"  <br>"6591558"   "6591567"  <br>"6729097").PN. | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:53 |
| S122 | 18 | (<br>"2785099"   "3204383"  <br>"3343314"   "3835604"  <br>"4103674"   "4333292"  <br>"4391075"   "4528790"  <br>"4545166"   "4637188"  <br>"4677903"   "4724651"  <br>"4735026"   "4819397").PN. OR<br>("5564250").URPN.  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>12:57 |
| S123 | 65 | (<br>"1763300"   "1850118"  <br>"1959880"   "2067403"  <br>"2082138"   "2574074"  <br>"3304683"   "3471981"  <br>"3653172"   "3787130"  <br>"3890755"   "4011697"  <br>"4054012"   "4076432"  <br>"4078847"   "4142335"  <br>"4205497"   "4275534"  <br>"4305677"   "4347015"  <br>"4350318"   "4356675"  <br>"4365453"   "4551957").PN. OR<br>("4688358").URPN.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>13:02 |

|      |     |   |                              |     |    |                     |
|------|-----|---|------------------------------|-----|----|---------------------|
| S124 | 38  | ("2221934"   "2990203"  <br>"3245188"   "3530996"  <br>"3532369"   "3666298"  <br>"3731958"   "3858989"  <br>"4090798"   "4194338").PN. OR<br>("4577449").URPN.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/09<br>13:06 |
| S125 | 258 | 52/289  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>10:45 |
| S126 | 111 | 52/285.1  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>11:02 |
| S127 | 38  | ("0095504"   "0405562"  <br>"0676509"   "0713871"  <br>"1094773"   "2793401"  <br>"2853751"   "2853752"  <br>"3018017"   "3146011"  <br>"3392497"   "3679280"  <br>"4098199"   "4158338"  <br>"4266386"   "4426935"  <br>"4796392"   "5212924"  <br>"5386788"   "5669495"  <br>"5724774"   "5960592"  <br>"6099197"   "6120206"  <br>"6286269"   "RE33263").PN. OR<br>("6786009").URPN. | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>11:07 |
| S128 | 304 | 52/643  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>11:20 |
| S129 | 485 | 52/655.1  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>11:31 |
| S130 | 503 | 52/262  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>11:43 |
| S131 | 18  | ("3762109"   "4018016"  <br>"4384317"   "4410930"  <br>"4718185"   "4754582"  <br>"5107637"   "5363608"  <br>"6295767"   "6415557"  <br>"D250836"   "D252215"  <br>"D336136"   "D338073"  <br>"D403434"   "D406352"  <br>"D436669"   "D438635").PN. OR<br>("7237360").URPN.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>11:45 |
| S132 | 817 | 52/263  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>12:07 |
| S133 | 302 | 52/585.1  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>13:18 |
| S134 | 0   | ("2003/0154672").URPN.  | USPAT                        | AND | ON | 2007/11/13<br>13:21 |

|      |      |  |                              |     |    |                     |
|------|------|--|------------------------------|-----|----|---------------------|
| S135 | 27   | ("1830382"   "2293569"  <br>"2396828"   "2600900"  <br>"2793401"   "3052291"  <br>"3308596"   "3727355"  <br>"3880405"   "4873797"  <br>"5167246"   "5184436"  <br>"5579796"   "5657583"  <br>"5778604"   "5921047"  <br>"6073404"   "6151843"  <br>"D404092").PN. OR ("6598363").<br>URPN.  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>13:23 |
| S136 | 1238 | 312/263  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>13:27 |
| S137 | 3553 | wall near support and roof   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>13:29 |
| S138 | 411  | (panel and roof) near support  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>13:30 |
| S139 | 8921 | panel near roof  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>13:41 |
| S140 | 48   | "building panel" near roof   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>13:41 |
| S141 | 54   | ("2151420"   "2269018"  <br>"2592634"   "2696102"  <br>"3292331"   "3566568"  <br>"3755982"   "3782049"  <br>"3988279"   "4038798"  <br>"4062822"   "4075808"  <br>"4130536"   "4194919"  <br>"4249354"   "4343125"  <br>"4439966"   "4523415"  <br>"4532745"   "4547331"  <br>"4550543"   "4613649"  <br>"4625484"   "4641468"  <br>"4774794"   "4787189"  <br>"4862660"   "4915539"  <br>"4924641"   "5081810"  <br>"5108679"   "5109088"  <br>"5123222"   "5162060"  <br>"5231813"   "5252636"  <br>"5322562"   "5347900"  <br>"5353562"   "5371990"  <br>"5393805"   "5485703"  <br>"5488806"   "5498683"  <br>"5519971"   "5540020"  <br>"5565535"   "5566521").PN. | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>13:42 |

|      |      |  |                              |     |    |                     |
|------|------|--|------------------------------|-----|----|---------------------|
| S142 | 65   | ("2744042"   "2851873"  <br>"3310917"   "3315424"  <br>"3398491"   "3446692"  <br>"3458609"   "3677874"  <br>"3803788"   "3874139"  <br>"3879908"   "4006570"  <br>"4015387"   "4038798"  <br>"4047357"   "4071984"  <br>"4079560"   "4090340"  <br>"4140824"   "4187651"  <br>"4226067"   "4236361"  <br>"4249354"   "4250670"  <br>"4253288"   "4288962"  <br>"4297820"   "4336676"  <br>"4340802"   "4342180"  <br>"4393636"   "4454702"  <br>"4455793"   "4486993"  <br>"4486996"   "4489530"  <br>"4505019").PN. OR ("4625484").<br>URPN. | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>13:43 |
| S143 | 24   | roof near boss   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>13:45 |
| S144 | 24   | "steel framed wall"  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>13:47 |
| S145 | 3    | "steel framed panels"  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>13:50 |
| S146 | 2332 | steel framed panels  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>13:50 |
| S147 | 196  | steel framed panels near roof  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>13:50 |
| S148 | 171  | steel framed panels near roof<br>(secured or locked or engaged or<br>interconnected)   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>13:51 |
| S149 | 1    | steel framed panels near roof<br>(secured or locked or engaged or<br>interconnected)   | EPO; JPO                     | AND | ON | 2007/11/13<br>13:57 |
| S150 | 1    | "3727355"  | EPO; JPO                     | AND | ON | 2007/11/13<br>14:13 |
| S151 | 16   | "3727355"  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>14:13 |
| S152 | 8    | "5758461"  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>14:15 |
| S153 | 27   | "3543456"  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>14:16 |
| S154 | 2479 | "flat roof"  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>14:17 |

|      |      |   |                              |     |    |                     |
|------|------|---|------------------------------|-----|----|---------------------|
| S155 | 118  | link near roof  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>14:46 |
| S156 | 61   | link near roof and walls  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>14:46 |
| S157 | 462  | roof ( "lap joints" or "laps splices"<br>or "dove tail joints" or "dowel<br>joints" or "pin fitting joints" or<br>"tongue and groove")  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>14:52 |
| S158 | 1    | S157 wal  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>14:55 |
| S159 | 301  | S157 wall   | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>14:55 |
| S160 | 7541 | girders   | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>15:59 |
| S161 | 200  | girders near (walls or panels)  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>16:00 |
| S162 | 150  | girders near (walls or panels)<br>(connected or engaged or<br>interconnected)   | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>16:00 |
| S163 | 724  | 312/265.5   | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>16:34 |
| S164 | 1    | "6892498"   | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/13<br>16:43 |
| S165 | 22   | ("20010029712"   "20020043038"<br>  "2732706"   "4698947"  <br>"5134826"   "5490357"  <br>"5860260"   "5887401"  <br>"5950396"   "6006480"  <br>"6112473"   "6173547"  <br>"6185898"   "6233892"  <br>"6237297"   "6305142"  <br>"6321496"   "6393782"  <br>"6401419"   "6571523"  <br>"6647686").PN. OR ("6892498").<br>URPN.  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>16:44 |
| S166 | 19   | "6250022"   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>16:59 |
| S167 | 43   | ("1365753"   "1416919"  <br>"1477867"   "1495439"  <br>"1716626"   "1835524"  <br>"3148230"   "3451183"  <br>"3511004"   "3687512"  <br>"3879914"   "4099815"  <br>"4145854"   "4147001"  <br>"4162114"   "4382046"  <br>"4388786"   "4683674"  <br>"4778309"   "4915540"  <br>"5155961"   "5412918"  <br>"5471806"   "5493839"  <br>"5511345"   "5634300"  <br>"5647181"   "5706620"  <br>"5797235"   "6099411"  <br>"6176053"   "6202867" | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>17:01 |

|      |      |  |                              |     |    |                     |
|------|------|--|------------------------------|-----|----|---------------------|
|      |      | "6250022"   "6250035").PN. OR<br>("6532707").URPN.   |                              |     |    |                     |
| S168 | 13   | ("20030140573"   "4570392"  <br>"4914874"   "5619826"  <br>"5647177"   "5682622"  <br>"5706613"   "6115971"  <br>"6250022"   "6418672"  <br>"6581337"   "6701678").PN. OR<br>("6892497").URPN.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>17:04 |
| S169 | 77   | ("0603147"   "2079635"  <br>"2270161"   "2981383"  <br>"3070646"   "3381430"  <br>"3436881"   "3452501"  <br>"3513608"   "3516216"  <br>"3543456"   "3638385"  <br>"3640039"   "3675380"  <br>"3820299"   "3854269"  <br>"3866381"   "3992839"  <br>"4258519"   "4294051"  <br>"4447099"   "4557091"  <br>"4652170"   "4805365"  <br>"5036634"   "5155961"  <br>"5184436"   "5221131"  <br>"5331778"   "5372415"  <br>"5386788"   "5398909"  <br>"5413236"   "5466058"  <br>"5529423"   "5575119"  <br>"5592794"   "5605344"  <br>"5622010"   "5647181"  <br>"5664380"   "5673531"  <br>"5724774"   "5775046"  <br>"5813738"   "5864997"  <br>"5975660"   "6047663"  <br>"6053591"   "6099092"  <br>"6105794"   "6113203"  <br>"6185878"   "6202867"  <br>"6250022"   "6357194"  <br>"D420838").PN. OR ("6701678").<br>URPN. | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/13<br>17:06 |
| S170 | 1797 | "concrete panels"  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/14<br>09:08 |
| S171 | 401  | "concrete wall panels"   | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/14<br>09:08 |
| S172 | 158  | "concrete wall panels" roof  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/14<br>09:08 |
| S173 | 0    | "concrete wall panels" roof "direct<br>bearing"  | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/14<br>09:08 |
| S174 | 74   | "concrete wall panels" roof<br>bearing   | US-PGPUB;<br>USPAT           | AND | ON | 2007/11/14<br>09:09 |
| S175 | 26   | ("0675648"   "1796048"  <br>"2001162"   "2202783"  <br>"2208814"   "2592634"  <br>"2664740"   "2703003"  <br>"2704935"   "3494092"  <br>"3555763"   "3693308").PN. OR<br>("3842558").URPN.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:21 |



|      |      |  |                              |     |    |                     |
|------|------|--|------------------------------|-----|----|---------------------|
| S176 | 305  | "concrete panels" (connect or engage or mount) roof  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:27 |
| S177 | 24   | ("1519319"   "2725241"  <br>"3330424"   "3655218"  <br>"3687300"   "3765543"  <br>"3765550"   "4481743"  <br>"4496277"   "4531720"  <br>"4676713"   "5042222"  <br>"5333981"   "5427495"  <br>"5551831"   "5690461"  <br>"5921738"   "5947665"  <br>"6341788"   "6592319").PN. OR<br>("6869261").URPN. | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:34 |
| S178 | 7    | S170 near tilt   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:45 |
| S179 | 2    | S170 near roof   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:46 |
| S180 | 88   | S170 tilt roof   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:46 |
| S181 | 2    | S170 near (connect or engage or interconnect or install) roof  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:48 |
| S182 | 286  | ("direct bearing connection") or<br>("pocket connections")   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:50 |
| S183 | 16   | ("direct bearing connection") or<br>("pocket connections") roof  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:51 |
| S184 | 3438 | ("direct bearing ") or ("pocket<br>connections")   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:52 |
| S185 | 3168 | ("direct bearing ") or ("pocket<br>connections") roof  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:52 |
| S186 | 3155 | ("direct bearing ") or ("pocket<br>connections") roof concrete   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:52 |
| S187 | 3155 | ("direct bearing ") or ("pocket<br>connections") roof concrete panels  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:52 |
| S188 | 3155 | ("direct bearing ") or ("pocket<br>connections") roof "concrete<br>panels"   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:52 |
| S189 | 3155 | ("direct bearing ") or ("pocket<br>connections") roof near "concrete<br>panels"  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:53 |
| S190 | 0    | ("pocket connections") roof near<br>"concrete panels"  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:53 |

|      |     |   |                              |     |    |                     |
|------|-----|---|------------------------------|-----|----|---------------------|
| S191 | 0   | ("direct bearing") roof near<br>"concrete panels"   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:54 |
| S192 | 0   | ("direct bearing") roof "concrete<br>panels"  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:55 |
| S193 | 0   | ("direct bearing") roof "concrete<br>panels"  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:55 |
| S194 | 21  | "517689"  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:55 |
| S195 | 0   | "517689".pn.  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>09:55 |
| S196 | 16  | "5608999"   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>11:40 |
| S197 | 1   | "5865001".pn.   | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>13:07 |
| S198 | 140 | (<br>"0518292"   "1124404"  <br>"1129658"   "1131479"  <br>"1238858"   "1313630"  <br>"1363391"   "1421007"  <br>"1436033"   "1439281"  <br>"1499572"   "1537278"  <br>"1592070"   "1757763"  <br>"1773168"   "1778345"  <br>"1834892"   "1840304"  <br>"2058285"   "2111577"  <br>"2184464"   "2208589"  <br>"2266007"   "2306548"  <br>"2321813"   "2451951"  <br>"2514805"   "2592634"  <br>"2630614"   "2723107"  <br>"2775019"   "2823426"  <br>"2823442"   "2902745"  <br>"2924962"   "2993637"  <br>"3146497"   "3245185"  <br>"3246828"   "3295818"  <br>"3310917"   "3317178"  <br>"3330437"   "3380703"  <br>"3415023"   "3434689"  <br>"3435580"   "3515779"  <br>"3553797"   "3638902"  <br>"3885008"   "3886699"  <br>"3892098"   "3930633"  <br>"3979863"   "4017051"  <br>"4033545"   "4090336"  <br>"4141532"   "4159100"  <br>"4163349"   "4194333"  <br>"4241555"   "4291513"  <br>"4365453"   "4380887"  <br>"4422997"   "4426060"  <br>"4432176"   "4494353"  <br>) | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>13:46 |

|      |    |  |                              |     |    |                     |
|------|----|--|------------------------------|-----|----|---------------------|
|      |    | "4512126"   "4532745"  <br>"4542613"   "4554124"  <br>"4570398"   "4605529"  <br>"4619032"   "4624089"  <br>"4641468"   "4751803"  <br>"4815243"   "4841702"  <br>"4862660"   "4934121"  <br>"4947600"   "4974381"  <br>"5055252"   "5313753"  <br>"5381635"   "5588272"  <br>"5697189").PN. |                              |     |    |                     |
| S199 | 7  | ("1124404").URPN.  | USPAT                        | AND | ON | 2007/11/14<br>14:04 |
| S200 | 14 | ("3719016").URPN.  | USPAT                        | AND | ON | 2007/11/14<br>14:05 |
| S201 | 15 | ("1653126"   "3574981"  <br>"3675885"   "3700202"  <br>"3727885"   "3885361"  <br>"4068427"   "4083156"  <br>"4872634"   "5322404"  <br>"5634301"   "5938391"  <br>"5943830"   "6029407").PN.  | US-PGPUB;<br>USPAT;<br>USOCR | AND | ON | 2007/11/14<br>14:44 |

11/14/2007 3:16:16 PM

C:\Documents and Settings\Ebrace\My Documents\EAST\Workspaces\10501451modular building.  
wsp